Touch-Free Infrared Thermometer

Model 09-348

These brief instructions allow you to quickly begin using your Infrared Touch-Free Thermometer for **Body Temperature Measurements**. Please refer to the Instruction Manual for more detailed instructions covering all features of the thermometer, including Object Temperature measurements.

- The infrared technology used in this thermometer is safe and is not harmful in any way. However, we recommend avoiding looking into the lens during use.

The Touch-Free Infrared Thermometer offers a selection of settings for use in the day or night and for person or object measurements.

To toggle between modes:

1. Press the **MEASURE** button to turn the thermometer on. The device will default the last mode used.
2. Press and release the **MODE** button to toggle through the four measurement options.



Person Mode

Object Mode

To measure body temperature using your Non-Contact Digital Infrared Thermometer, follow these steps:

1. Press the **MEASURE** button to turn the thermometer on. The unit will run a self-test and all symbols on the display will momentarily appear, *Fig. 1*.
2. The unit will beep twice and the display will show two solid dashes.
3. Aim the infrared lens at the individual's forehead, holding the thermometer approximately 0.5" – 1.0" away, *Fig 2*.
4. Press and hold the **MEASURE** button. The display will briefly show the mode, two dashes and a left facing arrow, *Fig. 3*.

   The thermometer will emit a single beep and the temperature reading will be displayed, *Fig. 4*.
5. If the temperature measurement is below 100.4° F, a happy face will be appear next to the reading. If the reading is 100.4° F or above, a sad face will be displayed and the red light will illuminate just below the display.
6. After 30-seconds of non-use, the thermometer will automatically beep and shut off.



Fig. 1

Fig. 2



Fig. 3

Fig. 4

IF YOU HAVE ANY QUESTIONS OR ARE EXPERIENCING DIFFICULTIES, PLEASE CALL THE TOLL-FREE CUSTOMER SERVICE HELP LINE FOR FURTHER ASSISTANCE AT 1-866-326-1313.

VERIDIAN HEALTHCARE®

#93-2056 05/15
©2015 Veridian Healthcare

QUICK START GUIDE • ENGLISH

Termómetro infrarrojo sin contacto para frente

Modelo 09-348

Estas breves instrucciones permiten comenzar rápidamente utilizando el Termómetro infrarrojo libre de toque para mediciones de **la temperatura corporal**. Consulte el Manual de instrucciones para obtener instrucciones más detalladas que cubre todas las funciones del termómetro, incluyendo mediciones de la temperatura del objeto.v.

- La tecnología infrarroja utilizada en este termómetro es segura y no es perjudicial en absoluto. Sin embargo, recomendamos evitar estudiando la lente durante el uso.

El Termómetro infrarrojo sin contacto brinda una variedad de configuraciones para usar durante el día o la noche y para tomar la temperatura a personas u objetos.

Para cambiar de un modo a otro:

1. Presione el botón **MEASURE** (medición) para encender el termómetro. Por defecto el dispositivo estará en el último modo que se utilizó.
2. Presione y suelte el botón **MODE** (MODO) para alternar entre las cuatro opciones de medición.



Modo Persona

Modo Objeto

Para medir la temperatura corporal con el Termómetro infrarrojo sin contacto, siga los pasos que se indican a continuación:

1. Presione el botón **MEASURE** (medición) para encender el termómetro. La unidad realizará un autodiagnóstico y en el visor aparecerán momentáneamente todos los símbolos, *Fig.* 1.
2. La unidad emitirá dos sonidos y en el visor aparecerán dos guiones. - -
3. Apunte el lente infrarrojo en frente de la persona, sosteniendo el termómetro aproximadamente 0,5"– 1.0", *Fig. 2*.
4. Presione y sostenga el botón **MEASURE** (medición). El display mostrará brevemente el modo, dos guiones y una flecha hacia izquierda, *Fig. 3*.

   El termómetro emitirá un pitido y la lectura de temperatura será exhibido, *Fig 4*.
5. Si la medición de temperatura es inferior a los 100,4° F, se visualizará una carita feliz al lado del valor de lectura. Si la lectura es igual o superior a los 100,4° F, se visualizará una carita triste y se encenderá la luz roja debajo del visor.
6. Luego de 30 segundos de no estar en uso, el termómetro emitirá una señal audible y se apagará en forma automática.



Fig. 1

Fig. 2



Fig. 3

Fig. 4

SI TIENE ALGUNA DUDA O EXPERIMENTA PROBLEMAS, LLAME A LA LÍNEA GRATUITA DE ASISTENCIA AL CLIENTE PARA OBTENER ASISTENCIA ADICIONAL, 1-866-326-1313.

VERIDIAN HEALTHCARE®

#93-2056 05/15
©2015 Veridian Healthcare

GUÍA DE REFERENCIA RÁPIDA • ESPAÑOL